

SRINIDHI YARD

No. 65 /B Tholkapiyar Street, TNHB,
Annalagraharam & Post,
Kumbakonam - 612401. Thanjavur - District.
Yard Incharge: 8072844356, Prop. : 8825463713

INVENTORY OF ITEMS IN VEHICLE

Date: 10/02/2024

BORROWER NAME : R. PREMNATH BANK OR FINANCE NAME :
AGREEMENT NO. : 43104494435 BRANCH : SBI : Thiruvindrapuram 10666
REGISTRATION NO. : MILLAGE :
MAKE & MODEL : NOV. 2023 ENGINE NUMBER : 3269543 1469
FUEL TYPE & COLOR : Diesel CHASIS NUMBER : TAT3T37BVP1100018
SARTHIMAN SUHARCANE HARVESTER BATTERY MAKE :

ENTRY MODE

No.	Inventory	Yes / No	No.	Inventory	Yes / No
1.	Number Plate		19.	Alloy Wheels	
2.	Side Dicky		20.	AC (Working / Not Working)	
3.	Side Indicator	✓	21.	Stereo / Radio	
4.	Keys (1,2)	.	22.	No. of Cassettes / CDS	
5.	RC Book (Original)	N.A	23.	LED TV	
6.	Warrenty Book / Manual	NA	24.	Aerial	
7.	Side / Door Mirror Right	✓	25.	Front Bumber	
8.	Side / Door Mirror Left	✓	26.	Rear Bumber	
9.	Horn		27.	Rear view Mirror - Driver	
10.	Seat Cover		28.	Door Mirro - Rear External	
11.	Tool kit		29.	Root Matting	
12.	Spanner		30.	Tarpaullin	
13.	Rope Rassi		31.	Wheel Caps	
14.	Stepni / Spare Tyre		32.	Jack	
15.	Tyre	✓	33.	Power Windows (Nil, Front, All)	
16.	Mod Flop (Nil, 1,2,3,4,5,6)		34.	Wiper Blade (Nil, 1,2,3)	
17.	Front Wind Shield		35.	Carpet (Nil, Front, Rear, Boot)	
18.	Rear Wind Shield		36.	Speakers (Nil, 1,2,3,4,5,6)	

Front Left Side	Good / Bad / Average	Front Right Side	Good / Bad / Average
Rear Left Side - 1	Good / Bad / Average	Rear Right Side - 1	Good / Bad / Average
Rear Left Side - 2	Good / Bad / Average	Rear Right Side - 2	Good / Bad / Average
Rear Left Side - 3	Good / Bad / Average	Rear Right Side - 3	Good / Bad / Average
Rear Left Side - 4	Good / Bad / Average	Rear Right Side - 4	Good / Bad / Average

DAMAGE REPORT

I hereby confirm the surrendering of the Assets to the Parking yard on behalf of the above bank (or) Finance and that no other valuable items VIZ ornaments (or) Documents (or) Cash were available in the said asset.

Name of the Yard Represnetative

E. K. R. R. R.

Signature

E. K. R. R. R.

Seal

For Srinidhi Yard

Proprietor

M. MAHESH

Name R. K. GANESH KUMAR

Agency Name SRI SKY ASSOCIATES.

SRINIDHI YARD

No. 65 /B Tholkapiyar Street, TNHB,
Annalagraharam & Post,
Kumbakonam - 612401. Thanjavur - District.
Yard Incharge: 8072844356, Prop. : 8825463713

INVENTORY OF ITEMS IN VEHICLE

Date: 10/02/2026

BORROWER NAME : PREM NATH. R BANK OR FINANCE NAME : SBI-1066
AGREEMENT NO. : A31049 94425 BRANCH : Thiruvindramvoor
REGISTRATION NO. : TN19BSA894 MILLAGE :
MAKE & MODEL : JOHN DEER, 07/2019 ENGINE NUMBER : M3029T335893
FUEL TYPE & COLOR : Diesel, Green CHASIS NUMBER : 1PY5210EVRJ020 446
JOHN DEER 31-5/428 BATTERY MAKE :

ENTRY MODE

No.	Inventory	Yes / No	No.	Inventory	Yes / No
1.	Number Plate	✓	19.	Alloy Wheels	
2.	Side Dicky		20.	AC (Working / Not Working)	
3.	Side Indicator		21.	Stereo / Radio	
4.	Keys (1,2)	✓	22.	No. of Cassettes / CDS	
5.	RC Book (Original)	N.A	23.	LED TV	
6.	Warrenty Book / Manual	N.A	24.	Aerial	
7.	Side / Door Mirror Right		25.	Front Bumber	
8.	Side / Door Mirror Left		26.	Rear Bumber	
9.	Horn		27.	Rear view Mirror - Driver	
10.	Seat Cover		28.	Door Mirro - Rear External	
11.	Tool kit		29.	Root Matting	
12.	Spanner		30.	Tarpaullin	
13.	Rope Rassi		31.	Wheel Caps	
14.	Stepni / Spare Tyre		32.	Jack	
15.	Tyre	✓	33.	Power Windows (Nil, Front, All)	
16.	Mod Flop (Nil, 1,2,3,4,5,6)		34.	Wiper Blade (Nil, 1,2,3)	
17.	Front Wind Shield		35.	Carpet (Nil, Front, Rear, Boot)	
18.	Rear Wind Shield		36.	Speakerss (Nil, 1,2,3,4,5,6)	

Front Left Side Good / Bad / Average ✓
Rear Left Side - 1 Good / Bad / Average ✓
Rear Left Side - 2 Good / Bad / Average ✓
Rear Left Side - 3 Good / Bad / Average ✓
Rear Left Side - 4 Good / Bad / Average ✓

Front Right Side Good / Bad / Average ✓
Rear Right Side - 1 Good / Bad / Average ✓
Rear Right Side - 2 Good / Bad / Average ✓
Rear Right Side - 3 Good / Bad / Average ✓
Rear Right Side - 4 Good / Bad / Average ✓

DAMAGE REPORT

I hereby confirm the surrendering of the Assets to the
Parking yard on behalf of the above bank (or) Finance and
that no other valuable items VIZ ornaments (or) Documents
(or) Cash were available in the said asset.

Name of the Yard Represnetative

Elayathala R

Signature

Elayathala R

For Srinidhi Yard

Seal

Proprietor
M. M. M. M. M.

Name R. K. GANESH KUMAR

Agency Name SRI SKY ASSOCIATES

SRINIDHI YARD

No. 65 /B Tholkapiyar Street, TNHB,
Annalagraharam & Post,
Kumbakonam - 612401, Thanjavur - District.
Yard Incharge: 8072844356, Prop. : 8825463713

INVENTORY OF ITEMS IN VEHICLE

Date: 10/02/2026

BORROWER NAME : R. PREM NATH BANK OR FINANCE NAME : SBI Thiruvananthapuram
AGREEMENT NO. : 431 044 94425 BRANCH : 1066 Thiruvananthapuram
REGISTRATION NO. : TN19BS 4847 MILLAGE :
MAKE & MODEL : 5210 - 07/2024 ENGINE NUMBER : PY3029T335910
FUEL TYPE & COLOR : Diesel CHASIS NUMBER : 1PY5210ECR5030440
JOHN DEER 31.5/42-8 BATTERY MAKE :

ENTRY MODE

No.	Inventory	Yes / No	No.	Inventory	Yes / No
1.	Number Plate	✓	19.	Alloy Wheels	
2.	Side Dicky		20.	AC (Working / Not Working)	
3.	Side Indicator		21.	Stereo / Radio	
4.	Keys (1,2)	✓	22.	No. of Cassettes / CDS	
5.	RC Book (Original)	N.A	23.	LED TV	
6.	Warrenty Book / Manual	N.A	24.	Aerial	
7.	Side / Door Mirror Right	✓	25.	Front Bumber	
8.	Side / Door Mirror Left	✓	26.	Rear Bumber	
9.	Horn		27.	Rear view Mirror - Driver	
10.	Seat Cover		28.	Door Mirro - Rear External	
11.	Tool kit		29.	Root Matting	
12.	Spanner		30.	Tarpaulin	
13.	Rope Rassi		31.	Wheel Caps	
14.	Stepni / Spare Tyre	✓	32.	Jack	
15.	Tyre		33.	Power Windows (Nil, Front, All)	
16.	Mod Flop (Nil, 1,2,3,4,5,6)		34.	Wiper Blade (Nil, 1,2,3)	
17.	Front Wind Shield		35.	Carpet (Nil, Front, Rear, Boot)	
18.	Rear Wind Shield		36.	Speakers (Nil, 1,2,3,4,5,6)	

Front Left Side Good / Bad / Average ✓
Rear Left Side - 1 Good / Bad / Average ✓
Rear Left Side - 2 Good / Bad / Average
Rear Left Side - 3 Good / Bad / Average
Rear Left Side - 4 Good / Bad / Average

Front Right Side Good / Bad / Average ✓
Rear Right Side - 1 Good / Bad / Average ✓
Rear Right Side - 2 Good / Bad / Average
Rear Right Side - 3 Good / Bad / Average
Rear Right Side - 4 Good / Bad / Average

DAMAGE REPORT

I hereby confirm the surrendering of the Assets to the Parking yard on behalf of the above bank (or) Finance and that no other valuable items VIZ ornaments (or) Documents (or) Cash were available in the said asset.

Name of the Yard Represnetative

Ebyasath A. K.

Signature

Ebyasath A. K.

Name R. K. GANESH KUMAR

Agency Name SRI SKY ASSOCIATES.

Seal

For Srinidhi Yard

M. MAMESH
Proprietor

M. MAMESH